


產品尺寸圖 (DIMENSION)



Symbol	Dimensions In Millimeters			Dimensions in Inches		
	Min	Nom	Max	Min	Nom	Max
A	-	-	2.997	-	-	0.118
A1	0.067	-	0.400	0.003	-	0.016
A2	2.300	-	2.819	0.091	-	0.111
b	0.300	0.400	0.500	0.012	0.016	0.020
C	0.100	-	0.300	0.004	-	0.012
D	25.450	-	26.187	1.002	-	1.031
E	11.140	-	11.430	0.439	-	0.450
e	1.270 BSC			0.050 BSC		
H	13.800	14.100	14.400	0.543	0.555	0.567
L	0.584	-	1.000	0.023	-	0.039
theta	0°	-	8°	0°	-	8°

Note : QC. Inspection Range : A,A1,A2,b,C,D,E,H

PACKAGE	SOP-40	
DRAWING NUMBER	DIM-SOP40-0412-A	
SIGNATURE	製圖	莊立德
	審核	陳建志
	核准	陳文椿